

0639Z 20 FEB 65

SECRET

TO : DIRECTOR

FROM : [REDACTED] 25X1A

ACTION:

INFO :

FOR 0708Z 20 FEB 65

PRIORITY

IN 73004

OPS 1-10 [Signature]

PRIORITY [REDACTED]

INFO [REDACTED]

QTE [REDACTED]

1700

25X1A

A. C0450

B. FAIR

C. NO MAJOR PROCESSING TROUBLES ENCOUNTERED. SOME PROCESSING STREAKS AND PIN HOLES NOTED.

CAMERA STATIC ON 9-R BURSTING ALONG BOTH EDGES

FROM HEAD TO TAIL, APPROX 1 INCH IN FROM EDGES.

MINUS DENSITY MARKS ON 9-L, 2 AND 3/4 INCHES IN

FROM THE CLOCK EDGE, AND REPEATING EVERY 1 AND 3/4 INCHES.

PLUS DENSITY LINE ON 9-R-PARTS, 1-2-3 ONLY, AND IS

3 AND 3/8 INCHES IN FROM THE OUTBOARD EDGE.

METERING TROUBLE ON 9-L-THE FIRST TWO FRAMES ARE OVERLAPPED.

END OF MSG

EDD [Signature]  
RS [Signature]  
RP [Signature]  
KB [Signature]  
WC [Signature]  
DB [Signature]  
NM [Signature]  
PA [Signature]  
RG [Signature]